

● PRINTER RUSH ●

(PTO ASSISTANCE)

Application : 101626657 Examiner : Friedhofer GAU : 2832

From : J. Black Location : (IDC) FMF FDC Date : 5/31/05

Tracking # : 06093862 Week Date : 9/11/05

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449		<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS		<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM		<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW		<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW		<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>7/25/03</u>	
<input type="checkbox"/> OATH		
<input type="checkbox"/> 312		
<input type="checkbox"/> SPEC		

Attn Chief Drafter per:

[RUSH] MESSAGE:

Drawings are traversed by broken line.

Please resolve.

[XRUSH] RESPONSE:

Corrected drawings

INITIALS:

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.




FIG. 1



FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9
PRIOR ART




FIG. 10
PRIOR ART